

Address:
Postal address:
Phone:
Fax:
E-mail:
Homepage:

Mechanic:
Date: 4/28/2017
Car licence no:
VIN:
Mileage:
Vehicle: Audi - Q7 - 2008

Fault codes

Diesel (BUN - TDI - MT/AT)

DTC	Description
U1007	- Please check fault codes in battery monitoring module - Permanent
P1195	- Fuel pressure control valve; open circuit/short circuit to ground - Intermittent

Brake (ABS/ESP - Mk25 E1)

DTC	Description
00668	- +30 voltage - Above upper regulation limit threshold - Intermittent

Instrument (Instrument - Diagnose)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Climate (Climate control - Climatronic "Basic")

DTC	Description
02380	- Positioning motor for right side ventilation - Mechanical error - Permanent
00447	- Function limitation due to over-voltage - No symptom - Intermittent
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Climate (Climate control - Climatronic "Comfort")

DTC	Description
02380	- Positioning motor for right side ventilation - Mechanical error - Permanent
00447	- Function limitation due to over-voltage - No symptom - Intermittent
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Gearbox (Gearbox - 09D)

DTC	Description
	No fault codes

Immobiliser (Immobiliser - EZS (Kessy) Advanced key)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent
00447	- Function limitation due to over-voltage - Above upper regulation limit threshold - Intermittent

Restraints (Airbag - 8R)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Multifunction (Battery regulation - Diagnose)

DTC	Description
02254	- Interface to generator - No communication - Intermittent
02479	- Partial consumer shut-off active - No symptom - Intermittent
02276	- Quiescent current stage 5 - No symptom - Intermittent
02256	- Quiescent current - Above upper regulation limit threshold - Intermittent
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Multifunction (Central electronics - Central electronics)

DTC	Description
02747	- Solenoid Bi-Xenon, right - Open circuit - Permanent
01495	- Lamp, left main beam - Short circuit to positive or open circuit - Permanent
00924	- Headlamp washer relay - Faulty - Permanent

Multifunction (Central electronics - Central electronics II)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent
00447	- Function limitation due to over-voltage - Above upper regulation limit threshold - Intermittent

Multifunction (Convenience system - Convenience system)

DTC	Description
01504	- Numberplate light - Short circuit to ground or open circuit - Permanent
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent
02957	- Light in the tail cover right - Short circuit to ground or open circuit - Permanent
03073	- Switch, boot lid closed - Faulty signal - Intermittent

Multifunction (Convenience system - Convenience system II)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent
02986	- Control unit roller blind roof function interruption - No symptom - Intermittent

Multifunction (Door electronics - Driver door)

DTC	Description
00920	- Mirror heating - Circuit failure - Permanent
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Multifunction (Door electronics - Passenger door)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Multifunction (Door electronics - Rear left door)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Multifunction (Door electronics - Rear right door)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Multifunction (Driver help system - Parking assistance)

DTC	Description
00447	- Function limitation due to over-voltage - Above upper regulation limit threshold - Intermittent
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Multifunction (Gateway - Diagnose)

DTC	Description
01207	- Parking/extra heater control unit - No communication - Permanent
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Multifunction (Infotainment - Control module information, front)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Multifunction (Infotainment - DSP (Sound system))

DTC	Description
	No fault codes

Multifunction (Infotainment - Media player position 1)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent
00532	- Voltage supply - Below lower regulation limit threshold - Intermittent

Multifunction (Infotainment - Navigation)

DTC	Description
00447	- Function limitation due to over-voltage - Above upper regulation limit threshold - Intermittent
02261	- Media player position 1 - Faulty - Permanent
03183	- Data medium not compatibly - No symptom - Intermittent
02927	- DVD read error - No symptom - Permanent

Multifunction (Infotainment - Radio)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent
00447	- Function limitation due to over-voltage - Above upper regulation limit threshold - Intermittent

Multifunction (Infotainment - Telephone)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent
02454	- Microphone unit - Short circuit to ground - Intermittent

Multifunction (Steering wheel electronics - Diagnose)

DTC	Description
00447	- Function limitation due to over-voltage - Above upper regulation limit threshold - Intermittent
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent

Multifunction (User/start access - EZS (Kessy) Advanced key)

DTC	Description
00532	- Voltage supply - Above upper regulation limit threshold - Intermittent
00447	- Function limitation due to over-voltage - Above upper regulation limit threshold - Intermittent