


GV2, GV3, and GV7 Manual Motor Starters, Controllers, and Protectors Specifications and Operating Curves

Table 36: Thermal-Magnetic Trip Curves for GV7R

Average operating time at 68 °F (20 °C) as a function of multiples of the setting current



1. Curve from cold state
2. Curve from hot state
3. 12–14 Ir
In the event of total phase failure, trip occurs after $4 \pm 20\%$