



Since this is a basic circuit diagram, the value of the parts is subject to be altered for improvement.

All DC voltage to be measured with a tester (100K Ω/V).


Voltage taken on a complex color bar signal including a standard color bar signal.

Unit for all resistors is ohm. K=1.000 ohm, M=1.000K ohm

Unit for all capacitors is μF. P = μμF

are fusible resistors.

BASIC CIRCUIT DIAG




www.microelectronic.co.yu

PRODUCT SAFETY NOTE

DIAGRAMME HFC-2111B

Components marked with a triangle and shaded have special characteristics important to safety. Before replacing any of these components read carefully the PRODUCT SAFETY NOTICE of this service manual. Don't degrade the safety of the receiver through improper servicing.



Remote control transmitter 